



PRODUCT INFORMATION

BOSTIK® TROWELS

Maximize Proper Coverage of Flooring Adhesive

PRODUCT DESCRIPTION








Trowel size is suggested to maximize coverage of adhesive. Periodically, check coverage of adhesive during installations; for moisture control 100% coverage is required for solid wood flooring that is less than 1/2" thick or any bamboo wood flooring; >95% coverage is required for all other wood flooring. For bonding only, check coverage to insure there is 80% coverage for engineered and >95% for all solid wood flooring and bamboo. Uneven subflooring may require the use of either a leveling/patching material, or a larger notched trowel for proper coverage of adhesive. These trowels are available from Bostik and from leading manufacturers such as Marshalltown (www.marshalltown.com).

PACKAGING

Sold in full cases only. 6 trowels/case.

TROWEL DESCRIPTION

ITEM NUMBER

Bostik #8 Flat/V-Notch Trowel	3/16"V x 1/4" deep x 1/2" centered		B11123
Bostik #18 Square-notch Trowel	1/8" wide x 1/8" deep		B11126
Bostik #9 V-notch Trowel	3/16" wide x 5/32" deep		B11127
Bostik #82 Square-notch Trowel	1/4" wide x 1/8" deep		B11124
Bostik #4 Square-notch Trowel	1/4" wide x 1/4" deep		B11125
Bostik/Marshalltown V-notch Trowel	1/2" wide x 15/32" deep		B15770
Bostik/Marshalltown V-notch Trowel	1/4" wide x 1/4" deep		B11170
Bostik/Marshalltown V-notch Trowel	3/16" wide x 1/4" deep		B15780

Bostik
Middleton, MA 01949
1-800-7/BOSTIK
1-800-726-7845

PLANT LOCATIONS
Temecula, CA 92590
Conyers, GA 30207
Paulsboro, NJ 08066



211 Boston Street • Middleton, MA 01949 • Customer Service and Technical Service 1-800-7/BOSTIK



09300

9

Wood Flooring
Bostik Trowels

August, 2010. Supersedes all previously published literature.

H18